

Zestawienie wyników analizy sitowej

Temat: Budowa nabrzeża portowego w Darłowie

nr otworu	głębokość pobrania [m]	Badania makroskopowe				Analiza uziarnienia							d10 [mm]	d60 [mm]	U
		Rodzaj gruntu	Barwa	Wilgotność	zawartość CaCO ₃	>2,0 mm	2,0 - 1,0 mm	1,0 - 0,5 mm	0,5 - 0,25 mm	0,25 - 0,125 mm	0,125 - 0,063 mm	<0,063 mm			
D-9	11,0	Pr+Ż	szarobrazowa	n	II	8,42%	19,04%	36,04%	30,48%	4,60%	0,90%	0,52%	0,30	0,75	2,54
D-4	6,0	Pd zap.	szary	n	III	0,16%	1,52%	2,72%	2,66%	19,74%	63,52%	9,68%	0,06	0,11	1,69
D-19	3,7	nB[PdH//Nmp]	czarna	n	I	6,60%	11,92%	20,60%	33,42%	19,72%	5,86%	1,88%	0,14	0,49	3,44
D-19	4,3	Po	szara	n	III	30,16%	10,54%	14,86%	23,72%	14,60%	4,62%	1,50%	0,16	1,04	6,44
D-15	4,8	Pd//T	szaro - czarny	n	II	0,15%	0,84%	1,92%	5,10%	69,01%	20,70%	2,28%	0,10	0,17	1,70
D-14	6,0	Pd	szara	n	II	0,00%	0,06%	0,08%	0,64%	72,02%	24,90%	2,30%	0,10	0,15	1,53